

No. in Book.	Steamer's Name. Material, Rig, &c.	Register's Tonnage.	Particulars of Classification.				Built.	Owners.	Register's Dimensions—Deck Erections, &c.			Port of Registry.	Engines.	Moulded Depth.	Registered in which classed, if not in L.R.
			Character.	For Special Survey.	Port of Survey.	Date when last seen.			Length.	Breadth.	Depth.				
Official No.	Late Name if any.	Gross.	Under Deck.	Net.	For Special Survey.	Date of last Survey.	When.	By Whom.				Flag.	No. & Dia. of Cylinders.—Stroke—Boiler Pressure. NHP—Horse power by Society's formula; RHP—power by Ship's Register. Particulars of Boilers & Furnaces. Engine Maker's Name.	Freeboard (midship).	Classed in which classed, if not in L.R.
Code Letters.	Special Surveys. No. of Decks, &c.						Where.								
64963	Aztec	SteelSc	5673				1914	W.Doxford & Sons, Ltd. Sunderland	390'3"	53'0"	30'2"	Haugesund	T.3Cy.26½" 44" & 74" 48"	379NH	C
MKGH	Wireless Fitted for oil fuel Elec.light Mchy.Ast Fitted with cylindrical tanks in holds for carrying petroleum	4678 1Dk 3468							P35'4"	H450'	F101'	Norwegian	W.Doxford & Sons, Ltd. Sld.		*
64964	Azul	SteelSc	5287				1919	Caird & Co. Ltd. Greenock	400'1"	52'3"	28'5"	London	T.3Cy.27" 44" & 73" 48" (s)	31 " 10	
142712	(ex Burgondier)	ssNpt.	4804				4mo	Ld. Greenock	P50' B113'	F39'		British	180lb	517NH	8 6 2
KVQM	Wireless Elec.light	1Dk (Stl)	3800				Lloyd's	Shanghai Dock Co. Shanghai	DTA1135t	FPT128t	APT14t	FR 7BHptCem	3SB, 9cf, as 190, Hs7668	FR 25 " 8	
64965	Azuma Maru	SteelSc	431				1914	Tokio Salvage Co. Ltd.	140'0"	26'5"	16'5"	Tokio	T.3Cy.12½" 28" & 46" 33"	120NH	
19293	(Tug & Salvage Steamer)		349									Japanese	Shanghai Dk Co. Shanghai		
NCJH	Wireless	1Dk	184				1918	Ishikawa	100'6"	24'2"	11'7"	Handa	C.2Cy.11½" & 21½" 14"	14NH	
64966	Azuma Maru No. 2	WoodAnx	199									Japanese	Ono Seikichi, Osaka		
23448		ScSr	181				1906	Nthmblnd	360'0"	48'0"	20'2"	Dairen	T.3Cy.25" 41" & 69" 48" (s)	30 " 10	
RDFH	Wireless	1Dk	186				5mo	S.B.Co.Ld. Newcastle	P30' B92'	F33'	28'0"	Japanese	180lb	372NH	8 6 2
64967	Azumasan Maru	SteelSc	4359				Lloyd's	K.K. Mitsui Bussan Kaisha, Ltd., Mgrs.	uE&B42'	154'	857'	APT150t	3SB, 9cf, as 150, Hs5940	FR 25 " 8	
67	(ex Purley)	ScSr	4079										Richardsons, Westgarth & Co. Ld. Sld.		
QBGS	Wireless	1Dk (Stl) & Spar dk (Stl) & deep framing	2709												

* * Additional Ships are inserted in the Supplement at the end of the Register.

N.B.—All vessels assigned a character in the Register Book are required, under the Rules of the Society, to be submitted to Surveys by the Society's Surveyors periodically (annually, if practicable), in order to its being seen that their efficiency is duly maintained. It is also a condition that all repairs of ships or machinery required at ports where there is a Surveyor to this Society, in order to their retaining the characters assigned to them in the Register Book, must be carried out under the inspection and to the satisfaction of the Society's Surveyors. Ships or Machinery repaired at ports where there is no Surveyor to this Society must be surveyed by one of the Society's Surveyors at the earliest opportunity.

The Date of Survey of a Ship only certifies to its efficiency at that time.

In reference to the Rules of the Society, and in order to prevent the disappointment arising from ships losing their characters from want of Survey, it is hereby intimated that the duty of giving Notice of Periodical Surveys required by the Rules, or when repairs are necessary in consequence of damage, or from other causes, rests with the Owners, Masters, or Agents.